

TABLE OF CONTENTS



US-BLW

**Wireless Handheld
Display**

Operation Manual

TABLE OF CONTENTS

Note: Please read the operation direction carefully before using weighing instrument. Thank you for your understanding.

TABLE OF CONTENTS

Chapter I Instrument Introduction	1
1. Overview	1
2. Technical Performances	1
Chapter II Definition of Interface	2
1. Wireless Transmitter Box	2
2. Wireless Instruments	2
Chapter III Calibration Debugs	3
1. Parameter Set	3
2. Weight Calibration	5
3. Compensation Calibration	6
4. Standardized Rate Modification & Calibration Debug Passwords	7
Chapter IV Operation Introduction	9
1. Introduction of Indicator Lamp	9
2. Boot to Zero & Reset Button	9
3. Net Weight	9
4. Weight Accumulation	9
5. Cumulative Weight Display	10
6. Cumulative Weight Clear	10
7. Information Prompts	10
8. Matters Needing Attention	10

CHAPTER I INSTRUMENT INTRODUCTION

1. Overview

The wireless weighing instrument consists of handheld wireless instrumentation and wireless transmitter box. It has benefits of weighing with high precision, long-term stability and high reliability of wireless communication. The operation is very easy and all electronic components accord with industrial-grade to ensure that work in harsh environments.

2. Technical Performances

1) Wireless transmitter box

- | | |
|---------------------------|---|
| a. Input Signal Range | -19.5~+19.5mV |
| b. A/D Conversion | 24-bit Sigma-Delta analog-to-digital Conversion |
| c. Nonlinear | $\leq 0.0015\%$ F.S. |
| d. Minimum Resolution | 0.5 μ V/d |
| e. Supply Voltage | 5V/300mA |
| f. Transmission Frequency | 433MHz (32 channels)/1200bps |
| g. Transmission Range | ≥ 350 m (No barrier) |
| h. Operating Temperature | -40~+85°C |
| i. Relative Humidity | $\leq 90\%$ R.H |
| j. Power Supply Voltage | DC7.2V |

2) Wireless Instruments

- | | |
|--------------------------|---|
| a. Display Screen | 6-bit 0.4-inch ultra bright LED display |
| b. Operating Temperature | -40~+85°C |
| c. Relative Humidity | $\leq 90\%$ R.H |
| d. Power Supply Voltage | Internal lithium battery 3Ah/6.4V; Outside DC7.2V |

CHAPTER II DEFINITION OF INTERFACE

1. F1 Wireless A/D transmitter box

a. Power Supply

The combination of two lines; red wire connect 6V, black line with 0V.

b. Sensor

Red line	Black line	Green line	White line
Bridge Voltage +	Bridge Voltage -	Signal+	Signal-

2. Wireless Instruments

The middle of power jack is positive supply DC7.2V, and the outside is Power Ground.

CHAPTER III CALIBRATION DEBUGS

Before the calibration debugging of an instrument, it is necessary to carefully check if the connection between the various parts is correct. If the connection has no problem, the next step is to open the case of instrument and plug the short block of circuit board SW1 in the instrument insert 1 and 2 feet. Then, it needs to be plugged in the instrument's power through **ON**. While the instrument finish its self- inspection program and enter into the weighing operation, it could be allowed to implement the calibration. After the calibration, the short block of circuit board SW1 must be plugged in the instrument insert 2 and 3 feet.

1. Parameter Set

No.	Key-Press	Display	Introduction
1	<p>Calibration</p> <p>8 8 8</p> <p>8 8 8</p> <p>Enter</p> <p>Enter</p>	<p>888888</p> <p>CAL 1</p>	<p>In Weighing Mode, press Calibration</p> <p>Initial Calibration Password: M1= 888888</p> <p>CAL= 1 Parameter Setting</p>
2	<p>1 0</p> <p>Enter</p>	<p>d **</p> <p>d 10</p>	<p>Weighing Scope Setting:</p> <p>d= 01, 02, 05, 10, 20, 50</p> <p>(e.g.) d= 10</p>
3	<p>0</p> <p>Enter</p>	<p>dC *</p> <p>dC 0</p>	<p>Decimal Point Setting:</p> <p>dC= 0, 1, 2, 3, 4</p> <p>0 - 0, 1 - 0.0, 2 - 0.00, 3 - 0.000, 4 - 0.0000</p> <p>(e.g.) dC= 0</p>

CHAPTER III CALIBRATION DEBUGS

4	<p>Clear</p> <p>5 0</p> <p>0 0 0</p> <p>Enter</p>	<p>*****</p> <p>50000</p>	<p>Range Setting:</p> <p>(e.g.) 50000kg</p>
5	<p>3</p> <p>Enter</p>	<p>F1.0 *</p> <p>F1.0 3</p>	<p>Zero Tracking Speed Setting:</p> <p>F1.0= 1,2,3,4(Slowest)</p> <p>(e.g.) F1.0= 3</p>
6	<p>2</p> <p>Enter</p>	<p>F1.1 *</p> <p>F1.1 2</p>	<p>Zero Tracking Range Setting:</p> <p>F1.1= 0, 1, 2, 3, 4, 5, 6</p> <p>Zero Tracking Range is $F1.1 * 0.5d$</p> <p>(e.g.) F1.1= 2</p>
7	<p>5</p> <p>Enter</p>	<p>F1.2 *</p> <p>F1.2 5</p>	<p>Boot Zero Range Setting:</p> <p>F1.2= 0, 1, 2, 3, 4, 5</p> <p>0 - Boot without Zero, 1 - 2%, 2 - 4%, 3 - 20%, 4 - 50%, 5 - 100%</p> <p>(e.g.) F1.2= 5</p>

CHAPTER III CALIBRATION DEBUGS

8	<p style="text-align: center;">5</p> <p style="text-align: center;">Enter</p>	<p style="text-align: center;">F1.3 *</p> <p style="text-align: center;">F1.3 5</p>	<p>Press →0← to set Zero Range:</p> <p>F1.3= 0, 1, 2, 3, 4, 5</p> <p>0 - Press →0← without Zero, 1 - 2%, 2 - 4%, 3 - 20%, 4 - 50%, 5 - 100%</p> <p>(e.g.) F1.3= 5</p>
9			<p>Back to Weighing Status</p>

2. Weight Calibration

No.	Key-Press	Display	Introduction
1	<p style="text-align: center;">2</p> <p style="text-align: center;">Enter</p>	<p style="text-align: center;">CAL 1</p> <p style="text-align: center;">CAL 2</p>	<p>To display CAL 1,</p> <p>CAL = 2 Weight Calibration</p>
2	<p style="text-align: center;">Enter</p>	<p style="text-align: center;">*****</p> <p style="text-align: center;">0</p>	<p>Display numerical value in empty electronic scale</p> <p>If display steadily, Press Enter</p>
3	<p style="text-align: center;">Enter</p>	<p style="text-align: center;">xxxxxx</p>	<p>Add Standard Weight G in Weighing Platform</p> <p>If display steadily, Press Enter</p>

CHAPTER III CALIBRATION DEBUGS

4	<div style="display: flex; justify-content: space-around; margin-bottom: 5px;"> 1 0 0 </div> <div style="display: flex; justify-content: space-around; margin-bottom: 5px;"> 0 0 </div> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">Enter</div>	<div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0; margin-bottom: 10px;">0</div> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">10000</div>	Input Standard Weight G (e.g.) G= 10000kg
5			Back to Weighing Status

3. Compensation Calibration

No.	Key-Press	Display	Introduction
1	<div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0; margin-bottom: 5px;">3</div> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">Enter</div>	<div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0; margin-bottom: 10px;">CAL 1</div> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">CAL 3</div>	To display CAL 1 , CAL= 3 Compensation Calibration
2	<div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">Enter</div>	<div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">xxxxxx</div>	Existent errors between Display Weight and Actual Weight G. Press Enter while steady presentation
3	<div style="display: flex; justify-content: space-around; margin-bottom: 5px;"> 1 0 0 </div> <div style="display: flex; justify-content: space-around; margin-bottom: 5px;"> 0 0 </div> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">Enter</div>	<div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0; margin-bottom: 10px;">0</div> <div style="border: 1px solid black; padding: 2px; width: fit-content; margin-left: 0;">10000</div>	Input actual Weight G (e.g.) G= 10000kg
4			Back to Weighing Status

CHAPTER III CALIBRATION DEBUGS

4. Standardized Rate Modification & Calibration Debug Passwords

No.	Key-Press	Display	Introduction
1	4 Enter	CAL 1 CAL 4	To display CAL 1, CAL= 4 Modifying Standardized Rate and Calibration Password M1
2	Enter	r1 *****	After 1 second, Display r1 (but r1 cannot be changed)
3	Enter	r2 *****	After 1 second, r2 Press numeric key to modify
4	8 8 8 8 8 8 Enter	F1 xxxxxx 888888	After 1 second, Calibration Password F1 Modification: Input new Calibration Password M1 (e.g.) Calibration Password M1= 888888
5			Back to Weighing Status

Warning:

- 1) The Standardized Rate cannot be allowed to modify randomly or the result of weighing process may be not accurate. Also, it is better not to change Calibration Debugging Password. If the Password has been modified, please must to remember because this instrument has no universal password. It has to

CHAPTER III CALIBRATION DEBUGS

return to the manufacturer for initialization if losing the password.

- 2) Please remember plugging the short block of circuit board in the instrument insert 1 and 2 feet is a premise for all of above Calibration Debugging Operation. After finishing the operation, users must plug the short block insert 2 and 3 feet and seal on the shell of instrument.

CHAPTER IV OPERATION INTRODUCTION

1. Introduction of Indicator Lamp

Indicator Lamp of stability: The weighing value is stable;

Indicator Lamp of gross weight: To display gross weight value;

Indicator Lamp of net weight: To display net weight value;


Indicator Lamp of zeroing: Gross weight value is 0

2. Boot to Zero & Reset Button


1) Boot to Zero


After self-inspection in boot, if the weight value is within boot zero range, it will display the weight value return to zero, or display the weight value not return to zero.

2) Press to Zero



Under weighing status, press . If the weight is within zero range by zero key, the weighing display will automatic zero resetting, or it does not return to zero.

3 Net Weight

In gross weighing state, the instrument displays the weight is stable and is greater than 0, press , the instrument will decrease tare weight and display net weight which is 0.

In the net weighing state, press , the instrument back to gross weight status after clearing the tare weight.

4 Weight Accumulation

In weighing status, the instrument displays the weight stability and greater than 0, press , the instrument automatically displays the cumulative weights and cumulative number of times ().

CHAPTER IV OPERATION INTRODUCTION

5 Cumulative Weight Display

In weighing mode, press **CUMULATIVE**, the instrument displays the cumulative number of times (**n *****); press **ENTER**, the instrument shows the cumulative weight of the high 3 (**H *****); press **ENTER** again, the instrument displays the cumulative weight of the low 5 (**L *******); and continues press **ENTER** to return to the weighing mode. In the process of the display of the cumulative weight, press **ESCAPE** to return to the weighing state directly.

6 Cumulative Weight Clear

In the weighing status, press **CLEAR**, the instrument displays **Y or N**, press **ENTER** to clear cumulative number of times and cumulative weights and back to weighing status; press **ESCAPE**, it does not clear data and back to weighing status directly.

7 Information Prompts

-----: Overload Alarm Signal. If this is a scale without debugging, the error signal will be eliminated after calibration.

Err01: Input wrong number.

Err02: No load weight on the scale which cannot be calibrated weight.

L: Indicates that the battery voltage is low which requires immediate charge.

--no--: Wireless signal failure.

8 Matters Needing Attention

- 1) To plug the sensor socket after turning off the instrument power supply.
- 2) If the left of the instrument displays L. please immediately using professional charger for charging on the instrument. The instrument should be charged every three month if there is no using in a long time.