


USM FLOOR SCALE ASSEMBLY GUIDE



Inside Scale:

- (1) Homerun Cable
- (1) Indicator w/ U-bracket
- (1) AC Adapter
- (1) Indicator manual
- (4) Screw in Feet

- 1.** Carefully open box and remove scale
- 2.** Locate access compartment (Top or Side) and remove the screws
- 3.** Remove all contents from inside compartment
NOTE: any upgrades to the order will be shipped separately, ie. indicator w/battery
- 4.** Route the homerun cable through the cable opening located inside the compartment near the underside of the scale
- 5.** Close compartment latch with screws
- 6.** Screw in all 4 feet into the 4 load cells located on the underside of each corner
NOTE: Do not screw in too deep that it will touch the platform
- 7.** Place scale on flat surface, if not level, lift scale slightly and adjust scale feet with a screwdriver through the feet access openings until the scale is stable
- 8.** Connect the homerun cable to the indicator
- 9.** Plug the AC adapter to the indicator and power on the indicator
- 10.** Once indicator is powered on, the display will count down show zero
- 11.** To ensure your scale is level, place an item you know the weight of on each corner of the scale, if a corner varies, adjustments to the feet should be made
- 12.** Your scale is ready for use (no calibration is needed)
- 13.** If the weight is incorrect, calibration will be needed

NOTE: Please refer to your indicator manual for proper calibration steps

Please call (800) 711-2237 ext. 2 for support questions

For updated indicator manual, please refer to www.usameasurements.com